

$$\Delta L = L_o \cdot \alpha \cdot \Delta T$$

$$\Delta S = S_o \cdot \beta \cdot \Delta T$$

$$\Delta V = V_o \cdot \gamma \cdot \Delta T$$

$$\beta = 2 \cdot \alpha$$

$$\gamma = 2 \cdot \alpha$$

$$\beta = 2 \cdot \alpha$$

$$\Delta S = S_o \cdot \beta \cdot \Delta T$$